

**INSPECTION BY STANFORD AFTER CAVITRON OPERATIONS**

1. Inspect K-10 Epoxy coating (per P0018)
2. Remove K-10 Epoxy coating (per P0017)
3. Cleaning (per P0016)
4. Perform General Inspection (per P0014) for:
  - a) Defects
  - b) Strain
  - c) R/O surface and chamfer
- 5) Check General Dimensions (per P0021) for:
  - a) OD
  - b) Total housing length
  - c) Jig holes
  - d) Surface flatness
6. Number Housings (per P0020)