

## **INSPECTION BY STANFORD OF FINISHED QUARTZ HOUSING**

1. Inspect K-10 Epoxy Coating (per P0018)
2. Remove K-10 Epoxy Coating (per P0017)
3. Perform Cleaning (per P0016)
4. Perform General Inspection (per P0014) for:
  - a) Defects
  - b) Strain
  - c) R/O Surface and Chamfer
5. Perform Inspection for General Dimensions (per P0021)
  - a) Surface flatness
  - b) Gas inlet and outlet holes
  - c) Instrumentation holes
  - d) Housing chamfer

