

INSPECTION BY STANFORD OF HOUSING BLANKS

1. Cleaning (per P0016)
2. Perform General Inspection (per P0014) for:
 - a) Defects
 - b) Strain
 - c) R/O Surface
3. Check General Dimensions (per P0021) for:
 - a) Surface flatness
 - b) Surface parallelism
 - c) OD, Length