

P0005  
March 1989  
S. Buchman

**ETCHING AND REINSPECTION BY STANFORD AFTER CAVITRON  
OPERATIONS**

1. Etch Quartz Housing (per P0015)  
(Surfaces to be protected: parting planes, back planes)
2. Perform Cleaning (per P0016)
3. Perform General Inspection (per P0014) for:
  - a) Defects
  - b) Strain
  - c) Cavity Chamfer
  - d) R/O surface
4. Check for Surface Flatness (per P0021)