

REMOVAL OF K-10 EPOXY RESIN

REMOVAL PROCEDURE

1. Soak for 12 hours in methylene chloride
2. Dump rinse in DI water
3. Rinse in methanol
4. Blow-dry with nitrogen