

**P0008**  
**March 1989**  
**S. Buchman**

**INSPECTION BY STANFORD OF TUMBLE LAPPED HOUSING**

1. Inspect Al-Ti Coating (per P0018)
2. Perform cleaning (per P0016)
3. Perform General Inspection (per P0014) for:
  - a) Defects
  - b) Strain
  - c) R/O Surface and and chamfer